


TRANSFORMING RETAIL THROUGH TECHNOLOGY



Retail Active 8000 - Serial COM Ports Engineering Change Notice


WHAT IS THIS NOTICE ABOUT?

The Retail Active 8000 has recently undergone a minor engineering change. The number of serial ports have now been expanded from 4 to 6. During this modification, the arrangement of these serial ports have been modified as part of the re-design process. The illustrations below show the changes between the two versions of the Retail Active

HOW DOES THIS AFFECT ME?

Please be aware of the modified order of the serial COM ports at the back of the new Retail Active 8000 (V2) units, so that your peripherals get connected properly. There are no other differences in operation.

RETAIL ACTIVE 8000 - VERSION 1



RETAIL ACTIVE 8000 - VERSION 2

